



BABCOCK Laboratories, Inc.
The Standard of Excellence for Over 100 Years

Client Name: Idyllwild Water District
Contact: Jerry Johnson
Address: P.O. Box 397
Idyllwild, CA 92549

Analytical Report: Page 1 of 4
Project Name: Idyllwild WD-DW-CC
Project Number: Annual

Report Date: 11-Sep-2017

Work Order Number: B7H2796

Received on Ice (Y/N): Yes Temp: 16 °C

Attached is the analytical report for the sample(s) received for your project. Below is a list of the individual sample descriptions with the corresponding laboratory number(s). Also, enclosed is a copy of the Chain of Custody document (if received with your sample(s)). Please note any unused portion of the sample(s) may be responsibly discarded after 30 days from the above report date, unless you have requested otherwise.

Thank you for the opportunity to serve your analytical needs. If you have any questions or concerns regarding this report please contact our client service department.

Sample Identification

<u>Lab Sample #</u>	<u>Client Sample ID</u>	<u>Matrix</u>	<u>Date Sampled</u>	<u>By</u>	<u>Date Submitted</u>	<u>By</u>
B7H2796-01	Zone 2 Station 2 ---ROUTINE---	Water	08/30/17 09:30	Jerry Johnson	08/30/17 12:52	Jerry Johnson
B7H2796-02	Zone 5 Station 10 ---ROUTINE---	Water	08/30/17 09:45	Jerry Johnson	08/30/17 12:52	Jerry Johnson



BABCOCK Laboratories, Inc.
The Standard of Excellence for Over 100 Years

Client Name: Idyllwild Water District
 Contact: Jerry Johnson
 Address: P.O. Box 397
 Idyllwild, CA 92549

Analytical Report: Page 2 of 4
 Project Name: Idyllwild WD-DW-CC
 Project Number: Annual

Report Date: 11-Sep-2017

Work Order Number: B7H2796

Received on Ice (Y/N): Yes Temp: 16 °C

Laboratory Reference Number

B7H2796-01

<u>Sample Description</u>	<u>Matrix</u>	<u>Sampled Date/Time</u>	<u>Received Date/Time</u>
Zone 2 Station 2	Water	08/30/17 09:30	08/30/17 12:52

Analyte(s)	Result	RDL	Units	Method	Analysis Date	Analyst	Flag
Anions							
Total Alkalinity	64	3.0	mg/L	SM 2320B	09/07/17 20:57	gv	
Hydroxide	ND	3.0	mg/L	SM 2320B	09/07/17 20:57	gv	
Carbonate	ND	3.0	mg/L	SM 2320B	09/07/17 20:57	gv	
Bicarbonate	64	3.0	mg/L	SM 2320B	09/07/17 20:57	gv	



BABCOCK Laboratories, Inc.

The Standard of Excellence for Over 100 Years

Client Name: Idyllwild Water District
Contact: Jerry Johnson
Address: P.O. Box 397
Idyllwild, CA 92549

Analytical Report: Page 3 of 4
Project Name: Idyllwild WD-DW-CC
Project Number: Annual

Report Date: 11-Sep-2017

Work Order Number: B7H2796

Received on Ice (Y/N): Yes Temp: 16 °C

Laboratory Reference Number

B7H2796-02

<u>Sample Description</u>	<u>Matrix</u>	<u>Sampled Date/Time</u>	<u>Received Date/Time</u>
Zone 5 Station 10	Water	08/30/17 09:45	08/30/17 12:52

Analyte(s)	Result	RDL	Units	Method	Analysis Date	Analyst	Flag
Anions							
Total Alkalinity	77	3.0	mg/L	SM 2320B	09/07/17 21:08	gv	
Hydroxide	ND	3.0	mg/L	SM 2320B	09/07/17 21:08	gv	
Carbonate	ND	3.0	mg/L	SM 2320B	09/07/17 21:08	gv	
Bicarbonate	77	3.0	mg/L	SM 2320B	09/07/17 21:08	gv	



BABCOCK Laboratories, Inc.
The Standard of Excellence for Over 100 Years

Client Name: Idyllwild Water District
Contact: Jerry Johnson
Address: P.O. Box 397
Idyllwild, CA 92549

Analytical Report: Page 4 of 4
Project Name: Idyllwild WD-DW-CC
Project Number: Annual

Report Date: 11-Sep-2017

Work Order Number: B7H2796

Received on Ice (Y/N): Yes Temp: 16 °C

Notes and Definitions

- ND: Analyte NOT DETECTED at or above the Method Detection Limit (**if MDL is reported**), otherwise at or above the Reportable Detection Limit (RDL)
- NR: Not Reported
- RDL: Reportable Detection Limit
- MDL: Method Detection Limit
- * / " : NELAP does not offer accreditation for this analyte/method/matrix combination

Approval

Enclosed are the analytical results for the submitted sample(s). Babcock Laboratories certify the data presented as part of this report meet the minimum quality standards in the referenced analytical methods. Any exceptions have been noted.

Nancy H. Boulineau For Cindy A. Waddell

cc: SDSHD

e-Short_No Alias.rpt

This report applies only to the sample(s) analyzed. As a mutual protection to clients, the public, and Babcock Laboratories, Inc., this report is submitted and accepted for the exclusive use of the Client to whom it is addressed. Interpretation and use of the information contained within this report are the sole responsibility of the Client. Babcock Laboratories, Inc. is not responsible for any misinformation or consequences that may result from misinterpretation or improper use of this report. This report is not to be modified or abbreviated in any way. Additionally, this report is not to be used, in whole or in part, in any advertising or publicity matter without written authorization from Babcock Laboratories, Inc. The liability of Babcock Laboratories, Inc. is limited to the actual cost of the requested analyses, unless otherwise agreed upon in writing. There is no other warranty expressed or implied.

mailing
P.O Box 432
Riverside, CA 92502-0432

location
6100 Quail Valley Court
Riverside, CA 92507-0704

P 951 653 3351
F 951 653 1662
www.babcocklabs.com

CA ELAP No. 2698
EPA No. CA00102
NELAP No. OR4035
LACSD No. 10119

